


Drive Shaft Repair Kits

Best range in the Aftermarket with over 20 References



Stub shafts are an unique development of VAG which can be found mainly in Transporter and Van applications.

The stub shaft transfers torque, absorbs vibrations and compensates length differences during suspension deflection to the drive shaft.



Why and when should a stub shaft be replaced?

As the stub shaft is exposed to environmental conditions and the outer splines are not covered by a boot, the wear of splines of stub and driveshaft is the main reason for vibrations and noises.

It is important to change the worn drive shaft together with the connecting stub shaft. If not, vibrations and noises occur provoked by the worn toothing of the old part. In case that only one part has been changed, the claims will come up again after short time. GSP now provides kits containing drive shaft and corresponding stub shaft to offer a service solution for workshops, which lowers the rework rate and allows a clever part replacement.

GSP has already over 20 references and is updating the range continuously.

Range table with short application

BRAND	STUB SHAFT	DRIVE SHAFT	MODEL	GEARBOX
VW	261190	203246	Transporter V+VI (2003-)	5MT
VW	261190	203261	Transporter V+VI (2003-)	5MT
VW	261190	203278	Transporter V+VI (2003-)	5MT
VW	261190	261105	Transporter V+VI (2003-)	5MT
VW	261191	203360	Transporter V+VI (2003-)	6MT
VW	261191	261084	Transporter V+VI (2003-)	6MT
VW	261191	261140	Transporter V+VI (2003-)	6MT
VW	261191	261210	Transporter V+VI (2003-)	6MT
VW/FORD/SEAT	261192	203023	Sharan/Galaxy/Alhambra 95-10	6MT
VW/FORD/SEAT	261192	261087	Sharan/Galaxy/Alhambra 95-10	6MT
VW/FORD/SEAT	261193	203023	Sharan/Galaxy/Alhambra 95-10	6MT
VW/FORD/SEAT	261193	261087	Sharan/Galaxy/Alhambra 95-10	6MT
VW	261213	261084	Transporter VI (2015-)	6MT
VW	261213	203261	Transporter VI (2015-)	6MT
VW	261216	203278	Transporter VI (2015-)	5MT
VW	261216	203246	Transporter VI (2015-)	5MT
AUDI/VW	261237	203355	Audi A3 (8P) / Touran I	GRF / GNE
VW	261238	203293	Transporter V+VI (2003-)	6AT

GSP drive shaft repair kits are always equipped with seal, lock rings and screws for quick repair in workshops.









